NOTICE TO MARINERS



DOGGER BANK OFFSHORE WIND FARM

DATE OF ISSUE:	31/07/2023
NOTICE TO MARINER NUMBER	LF700013-CST-DOG-NOT-0069

Dogger Bank C Export Cable Marine Hazard and Archaeological Exclusion Zone

LOCATION DESCRIPTION		Dogger Bank C Offshore Windfarm, Export Cable Corridor	
COORDINATES	DBC Export Cable Corridor	Marine Hazard 54° 44.74' N 000 17.62'E	
START DATE/TIME		31/07/2023	
END DATE/TIME		Until navigation charts have been updated	

Description of Hazard/Operation

Dogger Bank Offshore Windfarm is being developed in 3 phases – Dogger Bank A (DBA), Dogger Bank B (DBB) and Dogger Bank C (DBC), located off the North-east coast of England in the Southern North Sea.

A new marine hazard has been identified during UXO identification and investigation operations in the Dogger Bank C export cable corridor. The marine hazard is located on the seabed in the near vicinity of the intended route of the DBC export cable and is a group of metallic objects associated with military (probably WW2) activity in nature.

A 50 metre Archaeological Exclusion Zone (AEZ) has been implemented under the terms of the Written Scheme of Investigation (WSI) produced and agreed with Historic England as per Licence condition in accordance with 16(g) of dML 1 and Condition 13(g) of dML 3.

Fishing vessels and other vessels engaged in the deploying of sub-surface and bottom interacting gear should avoid the area.

Contact Details

Marine Coordination Contact	Duty Marine Coordinator Tel: +44(0)7586 332078 gm_dbmcc@equinor.com
Fisheries Liaison Officer (FLO)	Alex Winrow-Giffin, Brown & May Marine Ltd Alex@brownmay.com Tel: 01379 870181 Mob: 07760 160039 Zoë Lawrence - Brown & May Marine Ltd zoe@brownmay.com Mob: 07923 138175

NOTICE TO MARINERS



Supporting Information

Table 1 The coordinates of the marine hazard are provided below.

All locations referenced to WGS 84

ID	Degrees Decimal Minutes		
ID	Latitude	Longitude	
Marine hazard – Group of military, likely WW2, metallic objects	54° 44.74'N	000° 17.62'E	




Figure 1: Position of Marine Hazard in the Dogger Bank C Export Cable Corridor