

NOTICE TO MARINERS

DOGGER BANK OFFSHORE WIND FARM

DATE OF ISSUE:	08/03/2026
NOTICE TO MARINER NUMBER	LF500013-CST-DOG-NOT-0014 Rev 002

Dogger Bank A, B, C Navigation Warning Boundary Buoy

LOCATION DESCRIPTION	Dogger Bank A, B & C Offshore Windfarm, Construction Zones
DATE	28/01/2026

Description

Mariners are advised of the following defects that have been reported on the below listed Dogger Bank A, B and C construction area(s) boundary demarcation buoys:

Aid To Navigation	Position	Aid Type	Defect
DOGA East (Temp) (DBA-E1)	54° 48.815' N 002° 14.689' E	Lighted Buoy	Normal Conditions Restored
DOGA Golf (Temp) (DBA-SP7)	54° 46.402' N 002° 10.594' E	Lighted Buoy	Normal Conditions Restored
DOGA WSW (Temp) (DBA-S3)	54° 44.216' N 001° 37.550' E	Lighted Buoy	Normal Conditions Restored
DOGB Alpha (Temp) (DBB-SP1)	55° 05.554' N 001° 35.981' E	Lighted Buoy	Normal Conditions Restored
DOGB Foxtrot (Temp) (DBB-SP6)	54° 54.974' N 001° 52.086' E	Lighted Buoy	Normal Conditions Restored
DOGC E1 (Temp) (DBC-E1)	55° 02.953' N 002° 51.690' E	Lighted Buoy	Topmark Missing
DOGC S2 (Temp) (DBC-S2)	54° 57.251' N 002° 34.311' E	Lighted Buoy	Topmark Missing

Rectification of the listed defects will be notified to mariners on completion.

Contact Details

Marine Coordination Contact	Duty Marine Coordinator Tel: +44 (0) 7586 332078 gm_dbmcc@equinor.com
Fisheries Liaison Officer (FLO) CONTACT	Alex Winrow-Giffin, Brown & May Marine Ltd Alex@brownmay.com Tel: 01379 870181 Mob: 07760 160039 Zoë Lawrence - Brown & May Marine Ltd zoe@brownmay.com Mob: 07923 138175

Supporting Information




Figure 1: DBA and DBB Boundary Buoyage locations




Figure 2: DBC Boundary Buoyage locations