NOTICE TO MARINERS

DOGGER BANK WIND FARM

DOGGER BANK OFFSHORE WIND FARM

DATE OF ISSUE:	**07/11/2026**
NOTICE TO MARINER NUMBER	**LF500013-CST-DOG-NOT-0014 Rev 007**

Dogger Bank A, B, C Navigation Warning Boundary Buoy

LOCATION DESCRIPTION	**Dogger Bank A, B & C Offshore Windfarm, Construction Zones**
DATE	**07/11/2026**

Description

Mariners are advised of the following defects that have been reported on the below listed Dogger Bank A, B and C construction area(s) boundary demarcation buoys:

Aid To Navigation	Position	Aid Type	Defect
DOGA Foxtrot (SP6)	54° 50.612' N 002° 04.734' E	Special Mark	Unlit Topmark missing Daymark missing
DOGB East (E1)	54° 52.116' N 001° 52.166' E	East Cardinal	Topmark missing
DOGB North (N2	55° 06.289' N 001° 40.488' E	North Cardinal	Unlit
DOGC S1	54° 57.020' N 002° 57.366' E	South Cardinal	Topmark missing

Rectification of the listed defects will be notified to mariners on completion.

Contact Details

Marine Coordination Contact	**Duty Marine Coordinator** **Tel: +44 (0) 7586 332078** gm_dbmcc@equinor.com
Fisheries Liaison Officer (FLO) CONTACT	**Alex Winrow-Giffin, Brown & May Marine Ltd** **Alex@brownmay.com** **Tel: 01379 870181 Mob: 07760 160039** **Zoë Lawrence - Brown & May Marine Ltd** **zoe@brownmay.com Mob: 07923 138175**

Supporting Information




Figure 1: DBA and DBB Boundary Buoyage locations




Figure 2: DBC Boundary Buoyage locations